



Bill West Incorporated
887D Main Street
Monroe, CT 06468
203-261-6027 FAX 203-261-5061

TECH NOTE

July 18, 2008

Tech note for LV-677 - Changes in BIOS Rev 1.4

Date: 2007/08/09

Name: 67715.BIN

Message: LV-677 Version:1.5

Part number: 6A79KTP9

BIN file size: 4Mb

Checksum: 2000

Modify note:

1. Fixed 945GME display device can't identify.
 2. Modified SATA Mode : under DOS fixed to ATA-33's problem
 3. Add Virtualization Technology function.
 4. delete AHCI code 5 open CDIN function.
-

Date: 2007/08/09

Name: 677151.BIN

Message: LV-677 Version:1.51

Part number: 6A79KTP9

BIN file size: 4Mb

Checksum: 81EC

Modify note:

1. Modified under DOS TV-Out can't auto detect.
-

Date: 2008/05/22

Name: 67720.BIN

Message: LV-677 Version:2.0

Part number: 6A79KTP9

BIN file size: 4Mb

Checksum: C78D

Modify note:

1. Modified 1st. time Clear CMOS can't display's problem.
 2. Modified replaced ALC880 to ALC888 audio's problem.
-

Date: 2008/05/22

Name: 67720.BIN

Message: LV-677 Version:2.01

Part number: 6A79KTP9

BIN file size: 4Mb

Checksum: 813D

Modify note:

1. modified installed VGA Driver CRT resolution out of spec.

[END OF TECH NOTE]